



RESTAURANT PARAGRAPH

Elimination of odour nuisance through improved tightness of duct work.

Restaurant Paragraph

Location: Rapperswil, Switzerland

Date: October 2015

MEZ-AEROSEAL

Partner:

MEZ-TECHNIK GmbH

Result: The riser duct of the kitchen exhaust was

cleaned first. This made sealing with ME-ZAEROSEAL a really easy task, since the sealant could adhere to the leakage without problems. The kitchen exhaust duct was sealed 100%. The odour nuisance could be

completely eliminated.

Description

The kitchen exhaust duct of the Swiss traditional restaurant "Paragraph" was causing odour nuisance in the appartments above. Manual sealing efforts were not an option due to limited access to the duct work. Thus, the only possible solution was to seal the duct with MEZ-AEROSEAL.













Smell

Noise

Energy efficiency

Air tightness

quality

Successful sealing

With our successful MEZ-AEROSEAL partner network we achieve great success again and again.

The change in leakages

Before sealing

• 10 l/s

After sealing

• 0 1/s

Reduction

100%